


T. 135 R. 30 M. 5TH Coordinates: X _____ Y _____
NE 36 Corner common to sections 25, 36 AND 30, 31-135-29



EXISTING SURVEYS

Original Government Survey

Year surveyed 1858
 Original monument Post

Original Evidence Found

Year of search _____ By _____
 Monument found _____

Species	Bearing		Trees
	ELM	ELM	
Diameter	<u>8"</u>	<u>8"</u>	<u>12"</u>
Bearing	<u>S40W</u>	<u>S76E</u>	<u>N72E</u>
Distance	<u>35 LKS</u>	<u>10 LKS.</u>	<u>219 LKS.</u>

Original Bearing Trees Found

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

O = Corner

Subsequent Corner Restoration

Year surveyed 1999 By DNR J. Walker
 Location filed State of MN & CCSSO
 Monument Certificate of survey indicates nail and disk set.

Evidence of Subsequent Corner Restoration

Year of search JUNE 1997 By MN/DNR, J. WALKER
SET PK & ANR DISC IN BRIDGE DECK ON CR # 107 AT HOME BROOK
CERT. OF LOCATION, MAY 1999, DOC. # 412426

Bearing Trees, Reference Objects

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Bearing Trees, Reference Objects

<u>ANR RP IN SW WOOD CURB</u>	<u>SPRUCE</u>	_____	_____
<u>S60°W</u>	<u>18"</u>	_____	_____
<u>25.83</u>	<u>S74°E</u>	_____	_____
_____	<u>43.59</u>	_____	_____

V-25 Subsequent Corner Restoration

Evidence of Subsequent Corner Restoration Found

Year surveyed 6/2002 By CCSSO
 Location filed #2001.024
 Monument Found PK and DNR disk on bridge deck (Bridge replacement) witness as follows:

Year of search _____ By _____

- 18" Spruce S60°E, 43.59' DNR SRP
- 6" Ash N38°E, 46.78' *
- 8" Elm N36°W, 47.40' *
- P. Pole (BM) N5°W, 239.14' 90d spk
- P. Pole (BM) S45°W, 85.49' 90d spk

Oct. 1903 J. H. Hallett
Trap rd order shows survey