


Index No. J13

CASS COUNTY LAND CORNER RECORD

T. 135 R. 31 M. 5TH Coordinates: X _____ Y _____
NE 16 Corner common to sections 9, 10, 15, 16



EXISTING SURVEYS

Original Government Survey

Year surveyed 1870

Original monument POST

Species	Bearing	Trees	
<u>BR OAK</u>	<u>LIND</u>	<u>BALSAM</u>	<u>SPRUCE</u>
<u>4"</u>	<u>5"</u>	<u>5"</u>	<u>6"</u>
<u>S80W</u>	<u>N81W</u>	<u>N63E</u>	<u>S59E</u>
<u>16 LKS.</u>	<u>41 LKS.</u>	<u>31 LKS.</u>	<u>37 LKS.</u>

Original Evidence Found

Year of search _____ By _____

Monument found _____

Original Bearing Trees Found

Species _____

Diameter _____

Bearing _____

Distance _____

Subsequent Corner Restoration

Year surveyed _____ By _____

Location filed _____

Monument _____

Evidence of Subsequent Corner Restoration

Year of search 1992 12-22 By John D. Walker

Placed a 3/4 x 2 1/2" iron rod w/ aluminum cap stamped: "DNR
survey marker (up 0.1') 2' N of E-W fence, at Wedge
of a Swamp.

4-4-95 (Cert. Filed by John D. Walker, RLS 16098,
Doc. # 365899)

Bearing Trees, Reference Objects

Species _____

Diameter _____

Bearing _____

Distance _____

Bearing Trees, Reference Objects

<u>Oak</u>	<u>Oak</u>	<u>Fence Post</u>
<u>5"</u>	<u>5"</u>	<u>E-W-S</u>
<u>N24E</u>	<u>N34W</u>	<u>West</u>
<u>18.15</u>	<u>52.11</u>	<u>18.74</u>

Subsequent Corner Restoration

Year surveyed _____ By _____

Location filed _____

Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Remonumentation certificate prepared _____ By _____

Filed at _____ Date _____