


Index No. J 25

# CASS COUNTY LAND CORNER RECORD

T. 135 R. 32 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
NE 13 Corner common to sections 12, 13 AND 7, 18 - 135-31



13

## EXISTING SURVEYS

### Original Government Survey

Year surveyed 1858  
Original monument 6" BALSAM

### Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

	Bearing	Trees	
Species	<u>BL. ASH</u>	<u>BL. ASH</u>	<u>TAM.</u>
Diameter	<u>12"</u>	<u>9"</u>	<u>15"</u>
Bearing	<u>S52 1/2 E</u>	<u>S16 W</u>	<u>N14 1/2 E</u>
Distance	<u>19 LKS.</u>	<u>22 LKS.</u>	<u>29 LKS.</u>

	Trees
Species	<u>SPRUCE</u>
Diameter	<u>14"</u>
Bearing	<u>N65 1/2 W</u>
Distance	<u>80 LKS</u>

### Original Bearing Trees Found

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

○ = Corner

### Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

### Evidence of Subsequent Corner Restoration

Year of search \_\_\_\_\_ By \_\_\_\_\_

### Bearing Trees, Reference Objects

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

### Bearing Trees, Reference Objects

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

### Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

### Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_

Re monumentation certificate prepared \_\_\_\_\_  
Filed at \_\_\_\_\_

By \_\_\_\_\_  
Date \_\_\_\_\_