


T. 135 R. 32 M. 5th Coordinates: X _____ Y _____
NE 23 Corner common to sections 13, 14, 23, 24



EXISTING SURVEYS

Original Government Survey
 Year surveyed 1866
 Original monument Post

Bearing Trees
 Species BL. OAK
 Diameter 10"
 Bearing N 53 1/2 E
 Distance 428 LKS

Original Evidence Found
 Year of search _____ By _____
 Monument found _____

Original Bearing Trees Found
 Species _____
 Diameter _____
 Bearing _____
 Distance _____

Subsequent Corner Restoration
 Year surveyed 1915 By E.A. HORST
 Location filed COUNTY BOOK C P. 48
 Monument SET 1 1/2" x 48" I.P.
1920, E. L. TUSLER, COUNTY BOOK "C" P 376 FND I.P.
1915, R. BRYANT, BOOK "C" P 572 FND LARGE STONE
also on microfilm - roll 115 BK 71 P. 86

Evidence of Subsequent Corner Restoration
 Year of search _____ By _____
1915 - also on microfilm - roll 115 BK 71 P. 119
P. 126-127

Bearing Trees, Reference Objects
 Species OAK CFP
 Diameter 10"
 Bearing N 60-05W S 45-30E
 Distance 54.8' 46.5'

Bearing Trees, Reference Objects

Subsequent Corner Restoration
 Year surveyed 1985 8/28 By Terry Freeman
 Location filed _____
 Monument Fnd 1 1/2" I.P. down 0.4', 3' N. of
E-W Rd., 75' W. of E Rd 5.
also fnd 1915 tree CFP 545E 46.5 (steel)

Evidence of Subsequent Corner Restoration Found
 Year of search _____ By _____
PLAT - SWEAN VALLEY CEMETARY
R.K. WHITELEY 1896

R. oak 9" N 68W 60.70'
P.P. 545W 40.35'
show N look for orig B.T. NE 282.48'

Certificate - Walt Curo - 1985
Doc # 286246
accept fnd iron as corner - look for
orig B.T. - nothing found
Power Pole 545W 40.42'
9" Red Oak N 68W 60.70'
10" Red Oak N 12E 56.15'
Steel fence cor. 545E 46.31'