


T. 135 R. 32 M. 5TH Coordinates: X _____ Y _____
NE 26 Corner common to sections 23, 24, 25, 26



EXISTING SURVEYS

Original Government Survey

Year surveyed 1866
Original monument POST

Original Evidence Found

Year of search _____ By _____
Monument found _____

Species	Bearing	Trees	
<u>ASPEN</u>	<u>BL OAK</u>	<u>ASPEN</u>	<u>W. BIRCH</u>
<u>5"</u>	<u>6"</u>	<u>4"</u>	<u>8"</u>
<u>S69 1/4 E</u>	<u>N58 E</u>	<u>N37 W</u>	<u>S9 W</u>
<u>32 LKS.</u>	<u>11 LKS.</u>	<u>26 LKS.</u>	<u>25 LKS.</u>

Original Bearing Trees Found

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

O = Corner

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration

Year of search 9/16/85 By Terry Freeman
dug in intersection of roads N-S-E
dug 11' N-S X 11' E-W X 3.5' deep.
6" Class V, 1.5' fill, dug 1.5' into natural sandy clay.
Found nothing.
8/14/86 - set cast iron monument in intersection

Bearing Trees, Reference Objects

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Bearing Trees, Reference Objects

Species	Diameter	Bearing	Distance
<u>Telephone Pole</u>	<u>12"</u>	<u>N31°E</u>	<u>65.70'</u>
<u>Burr oak</u>	<u>3"</u>	<u>S86°W</u>	<u>200.60'</u>
<u>Burr oak</u>	_____	<u>S32°W</u>	<u>55.91'</u>

Certificate - Cur - 1987 - Doc # 297501

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
Certificate - Wa H Cur - 1987
May 1902; Twp rd order shows no survey
Dec. 1900; Twp rd order shows no survey