


Index No. V13

CASS COUNTY LAND CORNER RECORD

T. 135 R. 32 M. 5TH Coordinates: X _____ Y _____
NE 33 Corner common to sections 27, 28, 33, 34



EXISTING SURVEYS

Original Government Survey

Year surveyed 1866

Original monument Post

| Bearing Trees | |
|-------------------------|----------------|
| Species <u>W. PINE</u> | <u>W. PINE</u> |
| Diameter <u>22"</u> | <u>22"</u> |
| Bearing <u>NGSE</u> | <u>SRSE</u> |
| Distance <u>45 LKS.</u> | <u>35 LKS.</u> |

| Bearing Trees | |
|-------------------------|----------------|
| Species <u>W. PINE</u> | <u>W. PINE</u> |
| Diameter <u>24"</u> | <u>6"</u> |
| Bearing <u>SR6W</u> | <u>NRW</u> |
| Distance <u>70 LKS.</u> | <u>30 LKS.</u> |

Original Evidence Found

Year of search _____ By _____

Monument found _____

Original Bearing Trees Found

Species _____

Diameter _____

Bearing _____

Distance _____

O = Corner

Subsequent Corner Restoration

Year surveyed 1915 By E. B. HORST

Location filed County Book C P. 49

Monument I.M. 1 1/2 x 48" W.C. @ EAST CORNER
FALLS IN 3' DITCH.
1915, B. BRYANT, Book C P. 571 FIND OLD POST AND
I.B.T. also on MICROFILM - roll 115 BK 71
P. 84

Bearing Trees, Reference Objects

Species _____

Diameter _____

Bearing _____

Distance _____

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

1915 - 9/50 on microfilm - roll 115 BK 71 P 125,
127, 129

Bearing Trees, Reference Objects

Subsequent Corner Restoration

Year surveyed _____ By _____

Location filed _____

Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Remonumentation certificate prepared _____

By _____ Date _____