


T. 135 R. 32 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
NE 34 Corner common to sections 26, 27, 34, 35



EXISTING SURVEYS

Original Government Survey  
 Year surveyed 1866  
 Original monument Post

Original Evidence Found  
 Year of search \_\_\_\_\_ By \_\_\_\_\_  
 Monument found \_\_\_\_\_

Species	Bearing	Trees	Distance
<u>W. OAK</u>	<u>ASPEN</u>	<u>W. OAK</u>	<u>W. OAK</u>
<u>6"</u>	<u>8"</u>	<u>8"</u>	<u>7"</u>
<u>N75<sup>1</sup>/<sub>2</sub>W</u>	<u>S57<sup>1</sup>/<sub>2</sub>E</u>	<u>N31E</u>	<u>S47W</u>
<u>15 LKS.</u>	<u>12 LKS.</u>	<u>41 LKS.</u>	<u>44 LKS.</u>

Original Bearing Trees Found

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

O = Corner

Subsequent Corner Restoration  
 Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
 Location filed \_\_\_\_\_  
 Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration  
 Year of search 8/28/85 By Terry Freeman  
 Found 1 1/2" I.P. flush w/ road, top bent SE  
1' S. of & E. 3.5' E of N-S &  
7/29/86 - Replaced I.P. with Cast iron monument

Bearing Trees, Reference Objects

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Bearing Trees, Reference Objects

Species	Diameter	Bearing	Distance
<u>Twin Burr oak</u>	<u>4' 8"</u>	<u>N29°E</u>	<u>101.22'</u>
<u>Twin Burr oak</u>	<u>10"</u>	<u>N40°E</u>	<u>83.11'</u>
<u>Red oak</u>	<u>6"</u>	<u>S77°W</u>	<u>48.30'</u>
<u>Survey marker</u>	<u>sign</u>	<u>West</u>	<u>25.0'</u>

Corner Certificate - Curo - 1987 - Doc # 297506

Subsequent Corner Restoration  
 Year surveyed April 2004 By J. Leas # 42619  
 Location filed \_\_\_\_\_  
 Monument cert. of Sur. Shows mon. found.

Evidence of Subsequent Corner Restoration Found  
 Year of search \_\_\_\_\_ By \_\_\_\_\_  
Certificate - Walt Curo - 1987 Doc # 297506