


Index No. V 19

CASS COUNTY LAND CORNER RECORD

T. 135 R. 32 M. 5TH Coordinates: X _____ Y _____
N/4 35 Corner common to sections 26, 35



EXISTING SURVEYS

Original Government Survey

Year surveyed 1866
Original monument POST

Original Evidence Found

Year of search _____ By _____
Monument found _____

Bearing Trees

Species	<u>BC. PINE</u>	<u>Y. PINE</u>	_____
Diameter	<u>14"</u>	<u>14"</u>	_____
Bearing	<u>N78E</u>	<u>S39E</u>	_____
Distance	<u>54 LKS</u>	<u>16 LKS.</u>	_____

Original Bearing Trees Found

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

O = Corner

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration

Year of search 1985, 1986 By Surveyors office
9/19/85 - dug in E-W Rd and woods line N.
Dug 10' E-W x 9' N-S x 3' deep top 6" class V
1.5' fill, dug 1' into natural clay
8/14/86 - set cast iron in E-W Rd & woods
line N, as per measurements by Comstock & Davis

Bearing Trees, Reference Objects

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Bearing Trees, Reference Objects

<u>Red oak</u>	<u>Burr oak</u>	<u>Jack pine</u>
<u>3"</u>	<u>12"</u>	<u>TWIN 3"</u>
<u>N56°W</u>	<u>N22°W</u>	<u>N76°E</u>
<u>40.50'</u>	<u>75.55'</u>	<u>82.34'</u>

Certificate-Curo-1987- Doc # 297507
297507

Subsequent Corner Restoration

Year surveyed April 2004 By J. Leas # 42619
Location filed _____
Monument cert. of Sur. Shows mon. found

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
Certificate-walt Curo-1987

Remonumentation certificate prepared _____ By _____
Filed at _____ Date _____