


Index No. J 12-13

CASS COUNTY LAND CORNER RECORD

T. 136 R. 29 M. 5TH Coordinates: X _____ Y _____
M.C.# 25 Corner common to sections 9, 16



EXISTING SURVEYS

Original Government Survey
 Year surveyed 1870
 Original monument POST

Bearing Trees	
Species <u>N. PINE</u>	<u>N. PINE</u>
Diameter <u>14"</u>	<u>20"</u>
Bearing <u>N51W</u>	<u>S77W</u>
Distance <u>46 LKS.</u>	<u>62 LKS</u>

Original Evidence Found
 Year of search _____ By _____
 Monument found _____

Original Bearing Trees Found

Species _____	_____	_____
Diameter _____	_____	_____
Bearing _____	_____	_____
Distance _____	_____	_____

O = Corner

Subsequent Corner Restoration
 Year surveyed 1917 By E. B. HORST
 Location filed COUNTY BOOK "C" P. 148
 Monument FIND STUMP OF S.W. BT M.C FALLS IN LAKE
SET 2x48" I.M FOR W.C. M.C.
also on microfilm - roll 105 BK 64 P 81-82

Bearing Trees, Reference Objects	
Species <u>R. OAK</u>	<u>J. PINE</u>
Diameter <u>5"</u>	<u>6"</u>
Bearing <u>N30W</u>	<u>S45W</u>
Distance <u>41.0'</u>	<u>35.7'</u>

Evidence of Subsequent Corner Restoration
 Year of search 1949 By HAROLD LERO
COUNTY BOOK "D" P. 384 SET W.C. M.C.

Bearing Trees, Reference Objects	
Species <u>R. OAK</u>	<u>N. PINE or J. Pine?</u>
Diameter <u>10"</u>	<u>10"</u>
Bearing <u>N21-03E</u>	<u>S82-03W</u>
Distance <u>28.50'</u>	<u>41.90'</u>

Subsequent Corner Restoration
 Year surveyed _____ By _____
 Location filed _____
 Monument _____

Evidence of Subsequent Corner Restoration Found
 Year of search _____ By _____
PLAT - MILLER SHORES
MYRON LANDECKER 1978

Remonumentation certificate prepared _____ By _____
 Filed at _____ Date _____