


Index No. N 13

CASS COUNTY LAND CORNER RECORD

T. 136 R. 29 M. 5TH Coordinates: X _____ Y _____
NE 21 Corner common to sections 15, 16, 21, 22



EXISTING SURVEYS

Original Government Survey

Year surveyed 1870
Original monument POST

Original Evidence Found

Year of search _____ By _____
Monument found _____

Species	Bearing Trees			
	N. Pine	N. Pine	B. Pine	B. Pine
Diameter	<u>12"</u>	<u>10"</u>	<u>8"</u>	<u>9"</u>
Bearing	<u>S 55 E</u>	<u>S 47 W</u>	<u>N 71 E</u>	<u>N 51 W</u>
Distance	<u>48 LKS.</u>	<u>95 LKS.</u>	<u>65 LKS.</u>	<u>101 LKS.</u>

Original Bearing Trees Found				
Species				
Diameter	_____	_____	_____	_____
Bearing	_____	_____	_____	_____
Distance	_____	_____	_____	_____

O = Corner

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration

Year of search 1998 By CCSO
impl. 3/8" pin inside 1 1/2" OD I.P. the top 0.65' of the pin was bent when located.
fd. post "1 MN CONS. - FOR tag 25.2' N 60° W of corner.

Bearing Trees, Reference Objects

Species			
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Bearing Trees, Reference Objects

N. Pine	N. Pine	N. Pine	N. Pine
<u>18"</u>	<u>11"</u>	<u>11"</u>	<u>13"</u>
<u>N 29° W</u>	<u>S 80° E</u>	<u>S 36° E</u>	<u>S 34° W</u>
<u>62.25'</u>	<u>51.55'</u>	<u>63.46'</u>	<u>77.13'</u>

N-13

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
CERTIFICATE - GARY STEVENSON - DNR - 1978
DOC # 258660

Remonumentation certificate prepared _____ By _____
Filed at _____ Date _____