


Index No. V-12,13

CASS COUNTY LAND CORNER RECORD

T. 130 R. 29 M. 5TH Coordinates: X _____ Y _____

M.C. # 20 Corner common to sections 28, 33

WEST SIDE MAYO LAKE



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1870
Original monument POST

Original Evidence Found

Year of search _____ By _____
Monument found _____

Species	<u>TAM</u>	<u>B. PINE</u>	Bearing	Trees
Diameter	<u>6"</u>	<u>7"</u>		
Bearing	<u>N18W</u>	<u>S18W</u>		
Distance	<u>341ks</u>	<u>2471ks</u>		

Original Bearing Trees Found

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Bearing Trees, Reference Objects

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Bearing Trees, Reference Objects

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Remonumentation certificate prepared _____ By _____
Filed at _____ Date _____