Index No. V 7

CASS COUNTY LAND CORNER RECORD

T. 136 R. 29 M. 5TH Coordinates: X _____ Y _____

N1/4 32 Corner common to sections 29, 32



O = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1870

Original monument Post

Original Evidence Found

Year of search _____ By _____

Monument found _____

Bearing Trees

Species	B. Pine	B. Pine		
Diameter	12"	16"		
Bearing	S28W	N5E		
Distance	6 LKS	9 LKS		

Original Bearing Trees Found

Species				
Diameter				
Bearing				
Distance				

Subsequent Corner Restoration

Year surveyed May 2002 By CCSO

Location filed _____

Monument Found 2" OIP w/plumbers cap, up 0.2, at PI at trail.

Evidence of Subsequent Corner Restoration

Year of search 1/2003 By Landecker & Assoc

Found iron pipe with 2 1/2" plumbers cap.

Certificate filed

Bearing Trees, Reference Objects

Species	J. Pine	N. Pine	Aspen	N. Pine
Diameter	6"	10"	12"	8"
Bearing	N18°W	N18°E	S22°E	S80°W
Distance	71.83'	132.64'	12.09'	57.96'

Bearing Trees, Reference Objects

Species	J. Pine	Poplar	Poplar	Poplar
Diameter	8"	10"	12"	10"
Bearing	N14°W	N40°E	S32°E	S56°W
Distance	71.19'	23.43'	11.30'	16.05'

V-7

Subsequent Corner Restoration

Year surveyed _____ By _____

Location filed _____

Monument May 1925 J. Curo

Twp road order indicates corner

Feb. 2005 J. Leas #42619

Cert of Survey shows monument found

May 1925 John W. Curo

Twp road order shows survey

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Remonumentation certificate prepared ✓ By RLS 17008

Filed at CCRO document #462475 Date 2/14/03