


Index No. A 13

CASS COUNTY LAND CORNER RECORD

T. 136 R. 30 M. 5TH Coordinates: X _____ Y _____
NE 4 Corner common to sections 3, 4



EXISTING SURVEYS

Original Government Survey

Year surveyed 1870

Original monument C. C. Post

Species	Bearing	Trees	Distance
<u>W. Birch</u>	<u>W. Birch</u>		
<u>10"</u>	<u>6"</u>		
<u>S 35° E</u>	<u>S 35° 4W</u>		
<u>18 LKS</u>	<u>36 LKS.</u>		

Original Evidence Found

Year of search _____ By _____

Monument found _____

Original Bearing Trees Found

Species	Bearing	Distance
_____	_____	_____
_____	_____	_____
_____	_____	_____
_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1977 By R.F. Schneider

Location filed for Co. HWY Dept - CORP #28

Monument Corner position from road Stationing

Evidence of Subsequent Corner Restoration

Year of search 8/00 By CCSO

Fed 3" Alum. cap, 1.0' S. of E C.R. #28,
76'± E. of field ent. and 33'± E. of
fence line South.

Bearing Trees, Reference Objects

Species	Bearing	Distance
_____	_____	_____
_____	_____	_____
_____	_____	_____
_____	_____	_____

Bearing Trees, Reference Objects

N. Pine	N. Pine	N. Pine
<u>9"</u>	<u>10"</u>	<u>6"</u>
<u>S 58° E</u>	<u>S 4° E</u>	<u>S 42° W</u>
<u>113.90' *</u>	<u>55.65' *</u>	<u>87.12' *</u>

** distance to double head nail*

Subsequent Corner Restoration

Year surveyed _____ By _____

Location filed _____

Monument Corner GPS 9/12/02 CCSO
Alum cap

March 1903
Twp Road Order Shows no survey

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Re monumentation certificate prepared _____ By _____

Filed at _____ Date _____