

Index No. _____

CASS COUNTY LAND CORNER RECORD

T. _____ R. _____ M. _____ Coordinates: X _____ Y _____

Corner common to sections _____

= Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed _____
Original monument _____

Original Evidence Found

Year of search _____ by _____
Monument found _____

Bearing Trees

Species _____
Diameter _____
Bearing _____
Distance _____

Original Bearing Trees Found

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed: _____
Monument: _____

Evidence of Subsequent Corner Restoration

Year of search _____ By _____
Location filed: _____
Monument: _____

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed: _____
Monument: _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
Location filed: _____
Monument: _____

Index No. _____

CASS COUNTY LAND CORNER RECORD

T. _____ R. _____ M. _____ Coordinates: X _____ Y _____

Page _____ of _____

Corner common to sections _____

Subsequent Corner Restoration

Evidence of Subsequent Corner Restoration Found

Year surveyed _____ By _____
Location filed:
Monument:


Year of search _____ By _____
Location filed:
Monument:

EXCAVATION

Index No. J17

CASS COUNTY LAND CORNER RECORD

T. 136 R. 30 M. 5TH Coordinates: X _____ Y _____
NE 15 Corner common to sections 10, 11, 14, 15



EXISTING SURVEYS

Original Government Survey
 Year surveyed 1870
 Original monument POST

Original Evidence Found
 Year of search _____ By _____
 Monument found _____

Species	Bearing Trees			
	W. PINE	W. PINE	W. PINE	OAK
Diameter	<u>28"</u>	<u>16"</u>	<u>30"</u>	<u>14"</u>
Bearing	<u>S27W</u>	<u>S8E</u>	<u>N78E</u>	<u>N26W</u>
Distance	<u>75 LKS</u>	<u>100 LKS</u>	<u>130 LKS</u>	<u>125 LKS</u>

Original Bearing Trees Found

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

O = Corner

Subsequent Corner Restoration
 Year surveyed _____ By SURVEY OF S.R. HWY 80
 Location filed COUNTY BOOK "B" P 474-475
 Monument SPIKE
1920, E. B. HORST, BOOK "C" P 251 AND CORNER.

Evidence of Subsequent Corner Restoration
 Year of search 1940 By JOHN LURO
COUNTY BOOK "D" P 246-247 AND 2' SECTION OF 2x48"
I.P. DOWN DEEP INROAD
1921 - HORST - MICROFILM - roll 105 BK 67 P. 63
set 2x48" I.M. flush with top of HWY

Bearing Trees, Reference Objects

Species	Diameter	Bearing	Distance
<u>POPLAR</u>	<u>8"</u>	<u>NE</u>	<u>65.3'</u>
<u>TELE. POLE</u>	<u>8"</u>	<u>SE</u>	<u>37.4'</u>

1920 TIES.

Bearing Trees, Reference Objects

Species	Diameter	Bearing	Distance
<u>ELM</u>	<u>12"</u>	<u>N25E</u>	<u>196.2'</u>
<u>W. BIRCH</u>	<u>7"</u>	<u>S56E</u>	<u>123.70'</u>
<u>W. OAK</u>	<u>10"</u>	<u>S28-30W</u>	<u>76.5'</u>
<u>TWIN POPLAR</u>	<u>11"</u>	<u>N75-30W</u>	<u>110.00'</u>

1940 TIES

Subsequent Corner Restoration
 Year surveyed 1929 By _____
 Location filed _____
 Monument Co DITCH SURVEY BK 164 BOX
3 OF Co DITCH SURVEY BOOKS, PG 1

Evidence of Subsequent Corner Restoration Found
 Year of search _____ By _____

1/15/85 CORD & FREEMAN
FOUND PK @ P.I. & 1940 NE & SE BT'S
FAINT MAGNETIC READING 1 0.5' NNE OF PK
May 1919 Twp Rd order shows no survey

Remonumentation certificate prepared _____
 Filed at _____

By _____
 Date _____