

T. 136 R. 30 M. 5th Coordinates: X _____ Y _____
NE 14 Corner common to sections 11, 12, 13, 14



● = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1870
Original monument Post

Original Evidence Found

Year of search 1917 by Horst
Monument found _____
Survey Rec #338, Book B, pg 498

Bearing Trees

Species J. Pine J. Pine
Diameter 7" 8"
Bearing N 66° W N 70° E
Distance 200 links 95 links

Original Bearing Trees Found

Species Jack Pine
Diameter 8" stump
Bearing N 70° E
Distance 62.70'

Subsequent Corner Restoration

Year surveyed 5/1906 By W.H. Hallett, Surveyor
Location filed: Road Calendar Book A, pg 39 and Book B, pg 14
Monument:
Survey of County Road, indicates corner at intersection with Old Road running E. and W.

Evidence of Subsequent Corner Restoration

Year of search 4/1913 By Maple Township
Location filed: Final Road Order of Town Board
Monument:
Begin at corner

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed 3/1917 By E.B.Horst, LS 376
Location filed: Survey Record #338, Book B, page 498 and Curo
Monument: 2 1/2 x 48" I.M.
Curo Book 62, image 198, We begin at cor which sets in center of E & W graded road.
10" Jack Pine, N 30°30'W, 49.3'
7" Telephone Post, S57°25' W, 46.2'
12" Jack Pine, S 23°45' E, 70.1'

Evidence of Subsequent Corner Restoration Found

Year of search 3/2014 By CCHD/SO
Location filed: #2014.003
Monument: Found 2.5" ODIP, top badly damaged down 2.0', 4'+/-, N. of centerline CSAH #17, 4'+/-, E. of centerline 25th Ave. to S. and witnessed as follows.
Fence Corner, N 43° E, 47.42' duplex nail, up 1.0', E. side
6" White Oak, S 40° E, 89.42' duplex nail, up 1.0', E. side
Tele Ped Post, S 40° W, 65.23' duplex nail, up 1.0', E. side
Power Pole, N 38° W, 65.09' duplex nail, up 1.0', E. side

10/1929, A.W. Prudlo
C.A.R. #14, Ditch Shelf 3, Book 164, page 3
Indicates Sec. Cor. Iron pipe In place at Station 52+46.6
6" Pop, SW, 68.8' 6" Pop, SE, 60.5'
3/1951, D. Cole, Cass County Engineer
Project S.P. 11-509-01
Indicates corner assumed at PI station 52+45.7 at intersection of Twp. rd. S. and fence line N. witnesses the PI as follows
Power Pole, NE, 43.1' nail and disc
14" Poplar, SSW, 67.6' nail and disc
12" Poplar, WNW, 86.0' nail and disc

4/2020, CCHD/SO
#2018.019
After reconstruction of CSAH #17, set a 1"x 21" alum. Co. mon. over the recovered iron pipe, down 0.05', 4'+/-, E. of centerline of 25th Ave. and 3', N. of new centerline of CSAH #17.

5/2012, CCHD/SO
#2012.010
Found 2.5" ODIP, top badly damaged, down 2.0', 4'+/-, E. of centerline 25th Ave. to S. and 4'+/-, N. of centerline CSAH #17

