


Index No. E11

CASS COUNTY LAND CORNER RECORD

T. 136 R. 31 M. 5TH Coordinates: X _____ Y _____
N 1/4 9 Corner common to sections 4, 9



EXISTING SURVEYS

Original Government Survey
 Year surveyed 1870
 Original monument POST

Original Evidence Found
 Year of search _____ By _____
 Monument found _____

Bearing Trees
 Species ASPEN ASPEN
 Diameter 6" 8"
 Bearing S 70 W N 53 E
 Distance 4 LKS. 7 LKS

Original Bearing Trees Found
 Species _____
 Diameter _____
 Bearing _____
 Distance _____

Subsequent Corner Restoration
 Year surveyed 1913 By JOHN CURO
 Location filed COUNTY SURVEY RECORD BOOK "B" P12-28
 Monument SET 3x3x20" HUB PROPORTIONALLY
SET 2 1/2 x 48" GALV. I.P. IN CONCRETE

Evidence of Subsequent Corner Restoration
 Year of search Dec 2002 By CCSO
Found 2 1/2" O.D.P. w/ plumber cap, up
0.2' on East side of hill.

Bearing Trees, Reference Objects
 Species POPLAR POPLAR
 Diameter 6" 6"
 Bearing N 38-08E S 66-23E
 Distance 43.52' 44.15'

Bearing Trees, Reference Objects
W. Oak R. Oak R. Oak
5" 12" 6"
N 18° E S 60° E S 45° W
22.13' 6.69' 35.05'

Subsequent Corner Restoration
 Year surveyed _____ By _____
 Location filed _____
 Monument _____

Evidence of Subsequent Corner Restoration Found
 Year of search _____ By _____

Remonumentation certificate prepared A000668730
 Filed at _____

By _____
 Date _____