


Index No. E 15

CASS COUNTY LAND CORNER RECORD

T. 136 R. 31 M. 5TH Coordinates: X _____ Y _____
N 1/4 10 Corner common to sections 3, 10



EXISTING SURVEYS

Original Government Survey
 Year surveyed 1870
 Original monument Post

Bearing Trees
 Species W. Oak W. Oak
 Diameter 15" 18"
 Bearing S 70° E N 25° W
 Distance 15.44 19.46

Original Evidence Found
 Year of search _____ By _____
 Monument found _____

Original Bearing Trees Found
 Species _____
 Diameter _____
 Bearing _____
 Distance _____

○ = Corner

Subsequent Corner Restoration
 Year surveyed 1913 By John Curo
 Location filed County Survey Record Book B P. 12-28
 Monument SET HUB & TACK
SET 2 1/2 x 4 8" GALV. I.P. IN CONCRETE

Evidence of Subsequent Corner Restoration
 Year of search 1985 By Freeman-Mercum-Bunn
Find 2' I.P. @ intersection Rds N-S-E-W
ECLD tag on power pole NW

Bearing Trees, Reference Objects
 Species _____
 Diameter _____
 Bearing _____
 Distance _____

Bearing Trees, Reference Objects
Power pole C.F.P.
N 45° W S 53° W
49.95' 46.13'

E-15

Subsequent Corner Restoration
 Year surveyed 7/15/03 By CCSO
 Location filed _____
 Monument Set 7/8" ODIP, down 0.2', 1' ± S.
of 52nd St., 29' ± W. of Co Rd #25.

P. Pole N 11° W 35.85' dbl hd nail
P. Pole N 86° E 324.86' dbl hd nail
P. Pole S 4° W 212.51' dbl hd nail

Evidence of Subsequent Corner Restoration Found
 Year of search _____ By _____

6/1905 - Two Road Order, N.W. Hicks
Surveyor's Report shows stake by
Hallet 20.9 N. of a straight line.

Remonumentation certificate prepared A000668732
Filed at _____

By _____
Date _____