


Index No. N5

CASS COUNTY LAND CORNER RECORD

T. 136 R. 31 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
NE 19 Corner common to sections 17, 18, 19, 20



EXISTING SURVEYS

Original Government Survey  
 Year surveyed 1870  
 Original monument POST

Original Evidence Found  
 Year of search \_\_\_\_\_ By \_\_\_\_\_  
 Monument found \_\_\_\_\_

Species	Bearing	Trees	
<u>OAK</u>	<u>OAK</u>	<u>OAK</u>	<u>W. BIRCH</u>
<u>6"</u>	<u>7"</u>	<u>5"</u>	<u>7"</u>
<u>S40E</u>	<u>S20W</u>	<u>N46 1/2 W</u>	<u>N55E</u>
<u>32 LKS</u>	<u>23 LKS</u>	<u>7 LKS</u>	<u>12 LKS</u>

Original Bearing Trees Found

Species	Bearing	Distance

Subsequent Corner Restoration  
 Year surveyed 1922 By POST  
 Location filed COUNTY BOOK "D" P. 184  
 Monument 1 NO N.W. B.T STUMP SET I.M.

Evidence of Subsequent Corner Restoration  
 Year of search \_\_\_\_\_ By \_\_\_\_\_

Bearing Trees, Reference Objects

Species	Bearing	Distance
<u>WITNESS CORNERS</u>		
<u>I.M.S</u>		
<u>N45E</u>	<u>N45W</u>	
<u>46.7'</u>	<u>46.7'</u>	

Bearing Trees, Reference Objects

Species	Bearing	Distance

Subsequent Corner Restoration  
 Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
 Location filed \_\_\_\_\_  
 Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found  
 Year of search \_\_\_\_\_ By \_\_\_\_\_

Remonumentation certificate prepared \_\_\_\_\_ By \_\_\_\_\_  
 Filed at \_\_\_\_\_ Date \_\_\_\_\_