


Index No. P 13

CASS COUNTY LAND CORNER RECORD

T. 136 R. 31 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
E 1/4 R1 Corner common to sections 21, 22



EXISTING SURVEYS

Original Government Survey  
Year surveyed 1870  
Original monument Post

Original Evidence Found  
Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

Bearing Trees  
Species TAM TAM  
Diameter 1" 10"  
Bearing N13W S54E  
Distance 164s 204s

Original Bearing Trees Found  
Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Subsequent Corner Restoration  
Year surveyed 1913 By JOHN CURA  
Location filed COUNTY SURVEY RECORD BOOK "B" P. 12-28  
Monument SET HUB + TACK  
SET 2 1/2 x 48" GALV. IIP. IN CONCRETE

Evidence of Subsequent Corner Restoration  
Year of search 1986 By Dave Lundeker  
Corner Certificate - Doc # 297691  
Set cast iron monument proportionally - iron gone

Bearing Trees, Reference Objects  
Species TAM. Root TAM. Root  
Diameter DEAD DEAD  
Bearing S5E N38W  
Distance 12' 32.50'

Bearing Trees, Reference Objects  
Poplar Birch W. Pine  
5" 5" 30"  
N33°E N67°E N83°E  
59.80' 53.43' 116.47'

Subsequent Corner Restoration  
Year surveyed 5/99 By CCSO  
Location filed CCSO  
Monument CIM down 0.1', 2' West of  
E Co. Rd. #25

11" R. Oak, N8°W, 215.22', dbl hd nail  
7" Birch, N67°E, 53.43', 30d spike  
30" W. Pine, N83°E, 116.47', 30d spike

Evidence of Subsequent Corner Restoration Found  
Year of search \_\_\_\_\_ By \_\_\_\_\_  
Certificate - Dave Lundeker - 1986  
Doc # 297691

- Corner GPS 10/10/02 CCSO  
CIM, down 1.7', 2' ± W of E

Remonumentation certificate prepared \_\_\_\_\_ By \_\_\_\_\_  
Filed at \_\_\_\_\_ Date \_\_\_\_\_