


T. 136 R. 32 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
NE 1 Corner common to sections 1 AND 6 - 136-31



EXISTING SURVEYS

Original Government Survey

Year surveyed 1858  
Original monument POST

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

Bearing Trees  
Species W. BIRCH ASPEN  
Diameter 8" 8"  
Bearing 557°4E 526°42W  
Distance 42 LKS. 43 LKS.

Original Bearing Trees Found

Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Subsequent Corner Restoration

Year surveyed 1913 By JOHN CURE  
Location filed COUNTY SURVEY RECORD BOOK A' P 592-604  
Monument SET 2x2x30' OAK STAKE PULL STAKE  
SET 2 1/2 x 48" GALV. IP W/ CAP IN CONCRETE  
BOOK B' P. 12-28

Evidence of Subsequent Corner Restoration

Year of search May 2003 By C.C.S.O.  
~~CORNER GPS STAKES CASE~~  
Found 2 1/2" OD IP, w/ plumbers cap,  
cap 0.5' NE of small stump

Bearing Trees, Reference Objects

Species POPULAR  
Diameter 5 1/8"  
Bearing 55W  
Distance 15.30'

Bearing Trees, Reference Objects

* <u>W. Oak</u>	<u>W. Oak</u>	<u>W. Oak</u>	<u>W. Oak</u>
* <u>6"</u>	<u>9"</u>	<u>6"</u>	<u>4"</u>
* <u>N 47° W</u>	<u>N 38° E</u>	<u>S 36° E</u>	<u>S 18° W</u>
* <u>45.61'</u>	<u>39.07'</u>	<u>39.65'</u>	<u>10.31'</u>

\* = Dist. meas. to dbl hd nail

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument -Corner GPS 10/10/02 C.C.S.O.  
5/20/03 C.C.S.O.

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_