


Index No. V 1

CASS COUNTY LAND CORNER RECORD



T. 136 R. 32 M. 5TH Coordinates: X          Y           
NW, 31 Corner common to sections 30, 31 AND 25, 36-136-33

EXISTING SURVEYS

Original Government Survey

Original Evidence Found

Year surveyed 1858  
Original monument lost

Year of search          By           
Monument found         

	Bearing Trees			
	SP. PINE	SP. PINE	SP. PINE	SP. PINE
Species	<u>SP. PINE</u>	<u>SP. PINE</u>	<u>SP. PINE</u>	<u>SP. PINE</u>
Diameter	<u>6"</u>	<u>10"</u>	<u>7"</u>	<u>10"</u>
Bearing	<u>S66W</u>	<u>N74W</u>	<u>S70E</u>	<u>N82E</u>
Distance	<u>24 LKS</u>	<u>26 LKS</u>	<u>55 LKS</u>	<u>33 LKS</u>

Original Bearing Trees Found			
Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Subsequent Corner Restoration

Evidence of Subsequent Corner Restoration

Year surveyed 1962 By Miss DNR  
Location filed Office in St. Paul  
Monument End 2x48" IR.

Year of search          By           
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

Bearing Trees, Reference Objects

Bearing Trees, Reference Objects

	Bearing Trees, Reference Objects	
	J. Pine	F.P.
Species	<u>J. Pine</u>	<u>F.P.</u>
Diameter	<u>10"</u>	_____
Bearing	<u>SW</u>	<u>North</u>
Distance	<u>57.9'</u>	<u>26.9'</u>

Bearing Trees, Reference Objects			
Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Subsequent Corner Restoration

Evidence of Subsequent Corner Restoration Found

Year surveyed          By           
Location filed           
Monument         

Year of search          By           
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_