


Index No. A 11

CASS COUNTY LAND CORNER RECORD

T. 137 R. 29 M. 5TH Coordinates: X _____ Y _____
N 1/4 4 Corner common to sections 4 AND 33-138-29



EXISTING SURVEYS

Original Government Survey

Year surveyed 1865
Original monument Post

Bearing Trees

Species	<u>BL. PINE</u>	<u>ASPEN</u>	
Diameter	<u>5"</u>	<u>4"</u>	
Bearing	<u>N10E</u>	<u>S40E</u>	
Distance	<u>190 LKS.</u>	<u>133 LKS.</u>	

Original Evidence Found

Year of search _____ By _____
Monument found _____

Original Bearing Trees Found

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

O = Corner

Subsequent Corner Restoration

Year surveyed 1908, 1912 By John Curo, Harry Curo
Location filed COUNTY SUBVET RECORD BOOK "A" P 318-328
Monument SET CORNER FROM OLD GOVT BITS
IN 1912 FUNDLED GOVT B.T.: 5" BL. PINE
N10E 190 LKS. SET 2 1/2 x 48" CAPPED GALV I.P. IN
CONCRETE
also on MICROFILM - roll 115 BK 85 P. 213

Bearing Trees, Reference Objects

Species	<u>TELEPHONE POLE</u>	<u>WILLOW</u>	
Diameter	<u>4"</u>		
Bearing	<u>NW.</u>	<u>NE</u>	
Distance	<u>26.80'</u>	<u>58.50'</u>	

Evidence of Subsequent Corner Restoration

Year of search 1/31/92 By David Landecker
Set a 2" square county tubular monument
with stamped aluminum cap up 5".
Cert. Filed Doc. #335054

Bearing Trees, Reference Objects

<u>Burr Oak</u>	<u>Burr Oak</u>	<u>Red Oak</u>
<u>4"</u>	<u>8"</u>	<u>5"</u>
<u>N 34 W</u>	<u>N 7 W</u>	<u>N 64 E</u>
<u>22.86'</u>	<u>63.45'</u>	<u>33.62'</u>

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
2-4-92 Cert. Filed by David Landecker,
RLS 17008, Doc. #335054
Jan. 1992 D. Landecker #17008
Cert. of Survey shows monument found
NOV. 1908 John W. Curo
Two rd order indicates corner

Remonumentation certificate prepared _____ By _____
Filed at _____ Date _____