


Index No. D6

CASS COUNTY LAND CORNER RECORD

T. 137 R. 29 M. 5th Coordinates: X _____ Y _____
SW 1/4 Corner common to sections 5



EXISTING SURVEYS

Original Government Survey

Year surveyed _____
Original monument _____

Bearing Trees

Species _____
Diameter _____
Bearing _____
Distance _____

Original Evidence Found

Year of search _____ By _____
Monument found _____

Original Bearing Trees Found

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Evidence of Subsequent Corner Restoration

Year of search 1999 By Landecker & Assoc.
Ind. Cert. of Survey indicates
Ind. iron monument

Bearing Trees, Reference Objects

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Remonumentation certificate prepared _____ By _____

Filed at _____ Date _____