


Index No. J 25

CASS COUNTY LAND CORNER RECORD

T. 137 R. 30 M. 5TH Coordinates: X _____ Y _____
NE 13 Corner common to sections 12, 13 AND 7, 18-137-29



EXISTING SURVEYS

Original Government Survey

Year surveyed 1865

Original monument Post

Species	Bearing	Trees	
<u>ASPEN</u>	<u>ASPEN</u>	<u>ASPEN</u>	<u>ASPEN</u>
<u>5"</u>	<u>5"</u>	<u>5"</u>	<u>5"</u>
<u>N65E</u>	<u>N86W</u>	<u>SRE</u>	<u>-15W</u>
<u>45 LKS.</u>	<u>82 LKS.</u>	<u>36 LKS.</u>	<u>39 LKS.</u>

Original Evidence Found

Year of search _____ By _____

Monument found _____

Original Bearing Trees Found

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 5/2000 By CCSO

Location filed #99052

Monument Found & Located 7/8" ODIP, PLS #17253

Evidence of Subsequent Corner Restoration

Year of search 8/93 By B. Guvna #17253

Set IP and witnessed

Bearing Trees, Reference Objects

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Bearing Trees, Reference Objects

Species	Diameter	Bearing	Distance
<u>R. Oak</u>	<u>10"</u>	<u>S75°E</u>	<u>71.31'</u>
<u>R. Oak</u>	<u>12"</u>	<u>S46°E</u>	<u>84.79'</u>
<u>P. Pole</u>	<u>12"</u>	<u>S89°30'W</u>	<u>48.12'</u>
<u>Culvert</u>	<u>12"</u>	<u>N45°W</u>	<u>43.36'</u>

Subsequent Corner Restoration

Year surveyed _____ By _____

Location filed _____

Monument Corner GRS 9/17/02 CCSO
7/8" ODIP/w cap #17253, Flush on E

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Remonumentation certificate prepared _____ By _____

Filed at _____ Date _____