


Index No. P 25

CASS COUNTY LAND CORNER RECORD

T. 137 R. 30 M. 5TH Coordinates: X _____ Y _____
E 1/4 24 Corner common to sections 24 AND 19-137-29



EXISTING SURVEYS

Original Government Survey

Year surveyed 1865
Original monument POST

Original Evidence Found

Year of search _____ By _____
Monument found _____

Species	Bearing	Trees
<u>TAM</u>	<u>TAM</u>	
<u>7"</u>	<u>7"</u>	
<u>S 73 1/2 W</u>	<u>S 70 E</u>	
<u>74 LKS.</u>	<u>8 LKS.</u>	

Original Bearing Trees Found

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration

Year of search 2000 By CCSO
End. in place, capped I.P. RLS #17253. Located
E Co Rd. 1 and 18' N of E ext., and 179'± N of
S Wire Main OHP.

Bearing Trees, Reference Objects

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Bearing Trees, Reference Objects

Species	Diameter	Bearing	Distance
<u>W. Oak</u>	<u>10"</u>	<u>N 78° E</u>	<u>73.82'</u>
<u>W. Pine</u>	<u>10"</u>	<u>S 52° E</u>	<u>98.74'</u>
<u>P. Pole</u>		<u>N 31° W</u>	<u>72.84'</u>

(TAG)

*dist. to dbl. hd. nail

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument Aug 2002 R. Grivna 17253
Cert. of Surv. shows monument found.

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

-Corner GPS 9/17/02 CCSO
1" ODIR/w cap # 17253, flush on E

Remonumentation certificate prepared _____ By _____
Filed at _____ Date _____