


Index No. 215

CASS COUNTY LAND CORNER RECORD

T. 137 R. 30 M. 5TH Coordinates: X _____ Y _____
51434 Corner common to sections 34



EXISTING SURVEYS

Original Government Survey
 Year surveyed 1858
 Original monument POST

Original Evidence Found
 Year of search _____ By _____
 Monument found _____

Bearing Trees
 Species TAM TAM
 Diameter 13" 8"
 Bearing N58E N40W
 Distance 38LKS 4LKS

Original Bearing Trees Found
 Species _____
 Diameter _____
 Bearing _____
 Distance _____

Subsequent Corner Restoration
 Year surveyed 1917 By E.B. HORST
 Location filed COUNTY BOOK B, P. 565
 Monument SET 3x30" POPLAR POST
aka on microf. film - roll 115 BK 90 P. 67
1911. A.W. Moeber, microf. film - Roll 105 BK 49
SET 2x48" I.M. P. 133

Evidence of Subsequent Corner Restoration
 Year of search 1977 By R.E. Schneider for HW Dept
Co RD # 28
Corner position from road stationing

Bearing Trees, Reference Objects
 Species _____
 Diameter _____
 Bearing _____
 Distance _____

Bearing Trees, Reference Objects

Subsequent Corner Restoration
 Year surveyed 5/02 By CCSO
 Location filed _____
 Monument Found along cop monument 10'
S of E Co Rd. #28

Evidence of Subsequent Corner Restoration Found
 Year of search _____ By _____
- Corner GPS 9/17/02 CCSO
Along cap, 1' S. of #28

36" Cmp ~~1858~~ N56E 81.83' to PK
36" Cmp S50°E 80.37' to PK
14" W. Oak S62°W 232.87' to hd nail

Dec 2002 D. Landecker # 17008
Sketch and Description show
Mon. found