


Index No. 215

CASS COUNTY LAND CORNER RECORD

T. 137 R. 31 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
S1/4 34 Corner common to sections 34



EXISTING SURVEYS

Original Government Survey

Year surveyed 1858  
Original monument Post

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

Species	Bearing	Trees
<u>Aspen</u>	<u>7"</u>	<u>oak</u>
<u>14"</u>	<u>7"</u>	
<u>N33E</u>	<u>N15W</u>	
<u>7 LKS.</u>	<u>14 LKS.</u>	

Original Bearing Trees Found

Species	Diameter	Bearing	Distance

Subsequent Corner Restoration

Year surveyed 1920 By LINCOLN MACKAY  
Location filed COUNTY RESURVEY "E-46"  
Monument IRON MONUMENT  
1920, LINCOLN MACKAY, COUNTY BOOK "E" #2356 SET CORNER

Evidence of Subsequent Corner Restoration

Year of search 6/03 By CCSO  
Set 7/8" ODIP, no cap, down 0.3',  
6'± N. of & old road grade.

Bearing Trees, Reference Objects

Species	Diameter	Bearing	Distance

Bearing Trees, Reference Objects

Species	Diameter	Bearing	Distance
<u>R. Oak</u>	<u>7"</u>	<u>N34°E</u>	<u>29.70'*</u>
<u>R. Oak</u>	<u>10"</u>	<u>S56°E</u>	<u>56.52'*</u>
<u>Maple</u>	<u>15"</u>	<u>S38°W</u>	<u>58.30'*</u>

\*distance to double head nail →

Subsequent Corner Restoration

Year surveyed 7/15/03 By CCSG  
Location filed \_\_\_\_\_  
Monument Set 7/8" ODIP, down 0.3',  
9'± S. of & Co. Rd. #25.

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
June 1905 R. H. Hallett  
Two rd order shows survey

<u>11" W. Oak</u>	<u>S 44° W</u>	<u>82.94'</u>	<u>dbl hd nail</u>
<u>12" R. Oak</u>	<u>N 62° E</u>	<u>104.20'</u>	<u>dbl hd nail</u>
<u>P-Pole</u>	<u>S 80° E</u>	<u>156.95'</u>	<u>dbl hd nail</u>

Remuneration certificate prepared \_\_\_\_\_

By \_\_\_\_\_

Filed at \_\_\_\_\_

Date \_\_\_\_\_