


Index No. 23

CASS COUNTY LAND CORNER RECORD

T. 137 R. 31 M. 5TH Coordinates: X _____ Y _____
5/4 31 Corner common to sections 31



EXISTING SURVEYS

Original Government Survey

Year surveyed 1858
Original monument POST

Original Evidence Found

Year of search _____ By _____
Monument found _____

Species	Bearing	Trees
<u>Y. PINE</u>	<u>Y. PINE</u>	
<u>20"</u>	<u>26"</u>	
<u>N8E</u>	<u>N13W</u>	
<u>64 LKS.</u>	<u>27 LKS.</u>	

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1913 By Jordan Curo
Location filed COUNTY SURVEY RECORD BOOK 'A' P. 572-604
Monument FRAGILE GALT B.T. STUMPS 120" Y. PINE N8E
64 LKS. 26" Y. PINE N13W 27 LKS SET 2 1/2 X 48" GALV.
1/2" w/ CAP

Evidence of Subsequent Corner Restoration

Year of search _____ By _____
~~Corner GPS 5/22/03 case~~
Found 2 1/2" ODIP w/plumber cap, up
1.0', on slope North of swale.

Bearing Trees, Reference Objects

Species	Diameter	Bearing	Distance
<u>W. BIRCH</u>	<u>1</u>	<u>N66-37E</u>	<u>27.30'</u>
<u>PINE STUMP</u>		<u>N60-10W</u>	<u>34.20'</u>

Bearing Trees, Reference Objects

Species	Diameter	Bearing	Distance
<u>Maple</u>	<u>5"</u>	<u>North</u>	<u>* 12.94'</u>
<u>R. Oak</u>	<u>8"</u>	<u>S85°E</u>	<u>* 29.30'</u>
<u>N. Pine</u>	<u>16"</u>	<u>S18°W</u>	<u>* 74.81'</u>
<u>Pine Stump reman</u>		<u>N60°W</u>	<u>35"</u>

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument Corner GPS 5/22/03 case

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Remonumentation certificate prepared _____

By _____

Filed at _____

Date _____