


Index No. J19

CASS COUNTY LAND CORNER RECORD

T. 137 R. 32 M. 5TA Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
N 1/4 14 Corner common to sections 11, 14



O = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1870  
Original monument POST

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

Bearing Trees

Species DEAD TAM TAM \_\_\_\_\_  
Diameter 8" 7" \_\_\_\_\_  
Bearing S29W N3W \_\_\_\_\_  
Distance 30LKS 27LKS \_\_\_\_\_

Original Bearing Trees Found

Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Subsequent Corner Restoration

Year surveyed 1916 By E.B. HORST  
Location filed COUNTY BOOK "B" P. 545-549  
Monument SET 4x4 POST PROPORTIONALLY  
1917 - E.B. HORST - BOOK "C" P. 65 SET 2x4x8" I.M.  
also on microfilm - roll 115 BK 76 P. 53  
1916 - also on microfilm - roll 105 BK 65 P. 46

Evidence of Subsequent Corner Restoration

Year of search 1915 By \_\_\_\_\_  
Township road order shows no survey

Bearing Trees, Reference Objects

Species WIT. POSTS \_\_\_\_\_  
Diameter N45E, 545E \_\_\_\_\_  
Bearing 46.671 \_\_\_\_\_  
Distance 1916 \_\_\_\_\_

Bearing Trees, Reference Objects

\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_

Remonumentation certificate prepared \_\_\_\_\_  
Filed at \_\_\_\_\_

By \_\_\_\_\_  
Date \_\_\_\_\_