


Index No. \_\_\_\_\_

CASS COUNTY LAND CORNER RECORD

T. \_\_\_\_\_ R. \_\_\_\_\_ M. \_\_\_\_\_ Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_

Corner common to sections \_\_\_\_\_



= Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed \_\_\_\_\_  
Original monument \_\_\_\_\_

Original Evidence Found

Year of search \_\_\_\_\_ by \_\_\_\_\_  
Monument found \_\_\_\_\_

Bearing Trees

Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Original Bearing Trees Found

Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed:  
Monument:

Evidence of Subsequent Corner Restoration

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Location filed:  
Monument:

Bearing Trees, Reference Objects

Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Bearing Trees, Reference Objects

Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed:  
Monument:


Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Location filed:  
Monument:

Index No. L9

CASS COUNTY LAND CORNER RECORD

T. 137 R. 32 M. 5th Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
E 1/4 17 Corner common to sections 16, 17



EXISTING SURVEYS

Original Government Survey

Year surveyed 1870  
Original monument Post

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

Bearing Trees	
Species <u>SPRUCE</u>	<u>TAM.</u>
Diameter <u>11"</u>	<u>6"</u>
Bearing <u>S72W2E</u>	<u>N60W</u>
Distance <u>9 LKS</u>	<u>24 LKS.</u>

Original Bearing Trees Found

Species _____	_____	_____
Diameter _____	_____	_____
Bearing _____	_____	_____
Distance _____	_____	_____

○ = Corner

Subsequent Corner Restoration

Year surveyed 1913 By JOHN CURO  
Location filed COUNTY SURVEY RECORD BOOK "A" P. 592-604  
Monument FRU STAKE SET BY JOHN BURTON AND GLO 60 VT  
B.T. Root: 11" SPRUCE S72-30E 9 LKS SET 2 1/2 X 4 8"  
CALV. I.P. W/ CAN

Evidence of Subsequent Corner Restoration

Year of search Dec. 1915 By \_\_\_\_\_  
Township road order shows no survey  
April 1905; N. HICKS  
Township road order indicates corner

Bearing Trees, Reference Objects

Species <u>BIG STONE</u>	<u>BIG STONE</u>
Diameter <u>+</u>	<u>+</u>
Bearing <u>N84-33E</u>	<u>S13-35E</u>
Distance <u>144.17'</u>	<u>101.43'</u>

Bearing Trees, Reference Objects

_____	_____	_____
_____	_____	_____
_____	_____	_____
_____	_____	_____

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_

Remuneration certificate prepared \_\_\_\_\_ By \_\_\_\_\_  
Filed at \_\_\_\_\_ Date \_\_\_\_\_