


T. 137 R. 32 M. 5TH Coordinates: X _____ Y _____
5/4 32 Corner common to sections 32



EXISTING SURVEYS

Original Government Survey
Year surveyed 1858
Original monument Post

Original Evidence Found
Year of search _____ By _____
Monument found _____

Species	Bearing	Trees
<u>SPRUCE</u>	<u>ELM.</u>	
<u>16"</u>	<u>7"</u>	
<u>N47E</u>	<u>N43W</u>	
<u>46 LKS</u>	<u>18 LKS</u>	

Species	Bearing	Trees

Subsequent Corner Restoration
Year surveyed 1916 By E. B. HERST
Location filed COUNTY BOOK 'B' P. 542-544
Monument: FIND AN OLD TAIL, STAKE AND OLD GOUT BIT, STUMP: 7" ELM N43W 18 LKS AND ROTTEN 16" SPRUCE STUMP N47E 46 LKS. SET 4x4x48" POST
also on micro film - roll 105 BK 65 P. 20

Evidence of Subsequent Corner Restoration
Year of search 1917 By E. B. HERST
COUNTY BOOK 'C' P. 64 FIND WOOD POST SET FROM U.S. B.T.S. PULL POST - SET 2x48" I.M.
also on micro film - roll 115 BK 76 P. 46

Bearing Trees, Reference Objects
Species remark elm stump - no other trees near
Diameter _____
Bearing _____
Distance _____

Bearing Trees, Reference Objects

Subsequent Corner Restoration
Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found
Year of search _____ By _____

