


T. 138 R. 29 M. 5TH Coordinates: X _____ Y _____
NE 21 Corner common to sections 15, 16, 21, 22



O = Corner

EXISTING SURVEYS

Original Government Survey
 Year surveyed 1865
 Original monument Post

Bearing Trees			
Species	<u>BL. PINE</u>	<u>BL. PINE</u>	<u>BL. PINE</u>
Diameter	<u>6"</u>	<u>4"</u>	<u>5"</u>
Bearing	<u>N64E</u>	<u>N67W</u>	<u>S48E</u>
Distance	<u>51 LKS</u>	<u>106 LKS</u>	<u>9 LKS</u>

Original Evidence Found
 Year of search _____ By _____
 Monument found _____

Original Bearing Trees Found
 Species _____
 Diameter _____
 Bearing _____
 Distance _____

Subsequent Corner Restoration
 Year surveyed 1913 By JOHN CURO
 Location filed COUNTY SURVEY RECORD BOOK B P. 289-300
 Monument FIND OLD COURT BT STUMPS: 5" BL. PINE S48E 9 LKS, 4" BL. PINE S25W 7 LKS SET 3x3x20" HUB. SET 2x48" GALV. I.P. W/CHAIN CONCRETE.

Evidence of Subsequent Corner Restoration
 Year of search 1914 By F.A. Deane
microfilm - roll 115 BK 94 P. 87
Find Curo's Mon - run East
AUG. 2000 - CCSO
Find. Inplace 1 3/4" ODIP, down. 0.3'. 8'W of
♀ 12th Ave SW & ♀ 12th St. NW.

Bearing Trees, Reference Objects
 Species _____
 Diameter _____
 Bearing _____
 Distance _____

Bearing Trees, Reference Objects

<u>N. Pine</u>	<u>W. Pine</u>	<u>J. Pine</u>	<u>N. Pine</u>
<u>18"</u>	<u>5"</u>	<u>8"</u>	<u>6"</u>
<u>N 78°W</u>	<u>N 64°E</u>	<u>S 55°E</u>	<u>S 50°W</u>
<u>155.25'</u>	<u>38.92'</u>	<u>27.94'</u>	<u>33.94'</u>

(TAG)

Subsequent Corner Restoration
 Year surveyed _____ By _____
 Location filed _____
 Monument - Corner GPS 9/18/02 CCSO
1 1/2" ODIP, down 0.3', on ♀ W.,
9' W. of ♀ S.

Evidence of Subsequent Corner Restoration Found
 Year of search _____ By _____