


Index No. R 3

CASS COUNTY LAND CORNER RECORD

T. 138 R. 29 M. 5TH Coordinates: X _____ Y _____
N 1/4 30 Corner common to sections 19, 30



EXISTING SURVEYS

Original Government Survey

Year surveyed 1865
Original monument Post

Original Evidence Found

Year of search _____ By _____
Monument found _____

Bearing Trees

Species N. Pine N. Pine _____
Diameter 10" 10" _____
Bearing N 96 S 38 1/4 W _____
Distance 9 LKS 44 LKS. _____

Original Bearing Trees Found

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Bearing Trees, Reference Objects

R-3

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
PLAT - NORWAY NORTH SHORE
EDWARD ROBERTS 1946? 1947 JOHN W. CURRO
PLAT - PLEASANT VIEW ON NORWAY LAKE
JOHN E. HOWARD 1946

Remonumentation certificate prepared _____

By _____

Filed at _____

Date _____