


Index No. A 13

CASS COUNTY LAND CORNER RECORD

T. 138 R. 30 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
NE 4 Corner common to sections 3, 4 AND 33, 34 - 139-30



EXISTING SURVEYS

Original Government Survey  
 Year surveyed 1865  
 Original monument POST

Original Evidence Found  
 Year of search \_\_\_\_\_ By \_\_\_\_\_  
 Monument found \_\_\_\_\_

	Bearing Trees			
Species	<u>N. PINE</u>	<u>N. PINE</u>	<u>N. PINE</u>	<u>N. PINE</u>
Diameter	<u>22"</u>	<u>20"</u>	<u>20"</u>	<u>20"</u>
Bearing	<u>N 11 1/2 E</u>	<u>N 13 W</u>	<u>S 54 W</u>	<u>S 76 1/2 E</u>
Distance	<u>70 LKS.</u>	<u>54 LKS.</u>	<u>44 LKS.</u>	<u>83 LKS.</u>

Original Bearing Trees Found  
 Species \_\_\_\_\_  
 Diameter \_\_\_\_\_  
 Bearing \_\_\_\_\_  
 Distance \_\_\_\_\_

Subsequent Corner Restoration  
 Year surveyed 11-8-99 By PAT BUNAY, LANDLICK  
 Location filed \_\_\_\_\_  
 Monument FOUND CIM LS# 11395, 10/2/1987

Evidence of Subsequent Corner Restoration  
 Year of search MARCH 2000 By CCSO  
Find. impl, Brass Cap Mon., diam 0.3' & trail E/W and 21' N of trail to the south. RLS # 11395 (1987)

Bearing Trees, Reference Objects  
 Species \_\_\_\_\_  
 Diameter \_\_\_\_\_  
 Bearing \_\_\_\_\_  
 Distance \_\_\_\_\_

Bearing Trees, Reference Objects			
<u>R. Oak</u>	<u>R. Oak</u>	<u>R. Oak</u>	<u>R. Oak</u>
<u>3"</u>	<u>12"</u>	<u>12"</u>	<u>11"</u>
<u>NORTH</u>	<u>S 1° E</u>	<u>S 75° E</u>	<u>S 64° W</u>
<u>15.76'</u>	<u>30.19'</u>	<u>37.46'</u>	<u>50.35'</u>
	<u>(exist. B.T.)</u>	<u>(exist. B.T.)</u>	

A-13 Subsequent Corner Restoration  
 Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
 Location filed \_\_\_\_\_  
 Monument Mar 2005 B. Decidua #23044  
Cert. of Surv. shows mon. found  
10/99 - Landlick Assoc. Cert. of Survey indicates monument found

Evidence of Subsequent Corner Restoration Found  
 Year of search \_\_\_\_\_ By \_\_\_\_\_

Remonumentation certificate prepared \_\_\_\_\_ By \_\_\_\_\_  
 Filed at \_\_\_\_\_ Date \_\_\_\_\_