


Index No. A 7

CASS COUNTY LAND CORNER RECORD

T. 138 R. 30 M. 5TH Coordinates: X _____ Y _____
N 1/4 5 Corner common to sections 5 AND 32-139-30



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1865
Original monument Post

Bearing Trees

Species	<u>BL. PINE</u>	<u>BL. PINE</u>	_____
Diameter	<u>10"</u>	<u>7"</u>	_____
Bearing	<u>N 45E</u>	<u>S 8E</u>	_____
Distance	<u>33 LKS.</u>	<u>22 LKS.</u>	_____

Original Evidence Found

Year of search _____ By _____
Monument found _____

Original Bearing Trees Found

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1913 By JOHN CURE
Location filed COUNTY SURVEY RECORD BOOK "B" P. 289-300
Monument FWD HUB SET BY CURE SET 2x48' GALV. I.P.
W/ CAP IN CONCRETE

Evidence of Subsequent Corner Restoration

Year of search 1924 By Miss. Hwy. Dept
R/W map in Recorder's Office - Lathrop to Pine
River
2 1/2" I.P. in & Road.

Bearing Trees, Reference Objects

Species	<u>J. PINE</u>	<u>J. PINE</u>	_____
Diameter	<u>15"</u>	<u>12"</u>	_____
Bearing	<u>S 3-40 E</u>	<u>S 63-50 W</u>	_____
Distance	<u>3600'</u>	<u>24035'</u>	_____

Bearing Trees, Reference Objects

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 10/199 By Landecker & Assoc.
Location filed Two file
Monument Certificate of Survey indicates
monument found.

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
OCT 1994 B. GRIVNA
CEPT of SVY SHOWS MON FOUND

Remonumentation certificate prepared _____ By _____
Filed at _____ Date _____