


Index No. C5

CASS COUNTY LAND CORNER RECORD

T. 138 R. 30 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
E1/4 6 Corner common to sections 5, 6



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1865  
Original monument Post

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

Bearing Trees

Species	<u>Bl. Awn</u>	<u>Bl. Pine</u>	_____	_____
Diameter	<u>10"</u>	<u>10"</u>	_____	_____
Bearing	<u>S45W</u>	<u>S56E</u>	_____	_____
Distance	<u>25 LKS</u>	<u>33 LKS</u>	_____	_____

Original Bearing Trees Found

Species	_____	_____	_____	_____
Diameter	_____	_____	_____	_____
Bearing	_____	_____	_____	_____
Distance	_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1921 By E. B. Horst  
Location filed COUNTY RESURVEY E-39  
Monument Iron Monument - Govt B.T.  
1920, BEN CLARK, BOOK "C" P. 427 FNO GOVT BIT: 10"  
LINE S 6 E 21.8' AND OLD POST SET 2 1/2 X 30" I.M.

Evidence of Subsequent Corner Restoration

Year of search 1924 By Mrs. Horst Dept.  
RLW map in Recorder's Office - with map to  
Pine River  
Iron pipe.

Bearing Trees, Reference Objects

Species	<u>STONE</u>	_____	_____	_____
Diameter	<u>3' X 4"</u>	_____	_____	_____
Bearing	<u>S45W</u>	_____	_____	_____
Distance	<u>27.3'</u>	_____	_____	_____

Bearing Trees, Reference Objects

Species	_____	_____	_____	_____
Diameter	_____	_____	_____	_____
Bearing	_____	_____	_____	_____
Distance	_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_

Remonumentation certificate prepared \_\_\_\_\_

By \_\_\_\_\_

Filed at \_\_\_\_\_

Date \_\_\_\_\_