


Index No. E 15

CASS COUNTY LAND CORNER RECORD

T. 138 R. 30 M. 5TH Coordinates: X _____ Y _____
N 1/4 10 Corner common to sections 3, 10



EXISTING SURVEYS

Original Government Survey

Year surveyed 1865
Original monument Post

Original Evidence Found

Year of search _____ By _____
Monument found _____

Species	Bearing	Trees
<u>Bl. Pine</u>	<u>Bl. Pine</u>	
<u>3"</u>	<u>7"</u>	
<u>S 10 E</u>	<u>N 6 3/4 E</u>	
<u>44 LKS.</u>	<u>188 LKS</u>	

Original Bearing Trees Found

Species	Diameter	Bearing	Distance

Subsequent Corner Restoration

Year surveyed 6/2000 By CCSO
Location filed CCSO
Monument Set talspar mon. with Alum. cap, down 0.5', 4 1/2 N. of &

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Bearing Trees, Reference Objects

Species	Bearing	Reference Objects
<u>W. Oak</u>	<u>J. Pine</u>	<u>F. Post</u>
<u>6"</u>	<u>4"</u>	
<u>N 65° W</u>	<u>S 8° E</u>	<u>S 45° W</u>
<u>97.15'*</u>	<u>80.34'*</u>	<u>51.66'*</u>

* distance to double head nail

Bearing Trees, Reference Objects

Species	Diameter	Bearing	Distance

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument April 2004 B. Grivna # 17253
Cert. of Sur. Shows mon. found
March 2005 C. Hoglund # 43932
Cert. of Survey shows monument found

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Remonumentation certificate prepared _____ By _____
Filed at _____ Date _____