


T. 138 R. 30 M. 5TH Coordinates: X _____ Y _____
NE 22 Corner common to sections 14, 15, 22, 23



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1865
Original monument Post

Species	Bearing	Trees
<u>Bl. Pine</u>	<u>Bl. Pine</u>	<u>Bl. Pine</u>
<u>7"</u>	<u>8"</u>	<u>6"</u>
<u>N48 1/2 E</u>	<u>N57W</u>	<u>S48W</u>
<u>19 LKS</u>	<u>35 LKS</u>	<u>24 LKS</u>

Original Evidence Found

Year of search _____ By _____
Monument found _____

Original Bearing Trees Found

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed 1913 By John Curo
Location filed COUNTY SURVEY RECORD BOOK B' P. 289-300
Monument Find OLD GALT BIT STUMPS! 8" Bl. Pine N57W 35 LKS, 8" Bl. Pine S54E 33 LKS SET 2 1/2 x 48" GALT I.P. w/ 3" CAP IN CONCRETE

Bearing Trees, Reference Objects

Species	Bearing	Distance
<u>J. Pine</u>	<u>J. Pine</u>	
<u>10"</u>	<u>8"</u>	
<u>S41-25W</u>	<u>S56-28E</u>	
<u>47.77'</u>	<u>60.59'</u>	

Evidence of Subsequent Corner Restoration

Year of search 1985 By Walt Curo
Corner Certificate - Doc # 286249
Find 2 1/2" capped I.P. - lower monument 6"
Sign post west 33.00'

Bearing Trees, Reference Objects

Species	Bearing	Distance
<u>Power Pole</u>	<u>Red Oak</u>	<u>Red oak</u>
	<u>8"</u>	<u>12"</u>
<u>N45 E</u>	<u>S38E</u>	<u>S42W</u>
<u>49.45'</u>	<u>102.60'</u>	<u>62.00'</u>

N-17

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
Certificate - Walt Curo - 1985
May 1905 NW Hicks
Trwp rd order shows survey