


Index No. _____

CASS COUNTY LAND CORNER RECORD

T. _____ R. _____ M. _____ Coordinates: X _____ Y _____

Corner common to sections _____



= Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed _____
Original monument _____

Original Evidence Found

Year of search _____ by _____
Monument found _____

Bearing Trees

Species _____
Diameter _____
Bearing _____
Distance _____

Original Bearing Trees Found

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed:
Monument:

Evidence of Subsequent Corner Restoration

Year of search _____ By _____
Location filed:
Monument:

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____


Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed:
Monument:

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
Location filed:
Monument:

T. 13B R. 30 M. 5TH Coordinates: X _____ Y _____
NE 34 Corner common to sections 26, 27, 34, 35



EXISTING SURVEYS

Original Government Survey

Year surveyed 1865
Original monument POST

Bearing Trees			
Species	N. PINE	N. PINE	N. PINE
Diameter	<u>20"</u>	<u>20"</u>	<u>12"</u>
Bearing	<u>N 50 1/2 E</u>	<u>N 44 W</u>	<u>S 39 W</u>
Distance	<u>87 LKS</u>	<u>65 LKS.</u>	<u>105 LKS.</u>

Original Evidence Found

Year of search _____ By _____
Monument found _____

Original Bearing Trees Found

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1912 By JOHN CURD
Location filed COUNTY SURVEY RECORD BOOK "A" P. 454-455
Monument SET 2x48" CAPED, GALV. I.P. IN CONCRETE FROM OLD GARD. B.T. STUMPS.

Evidence of Subsequent Corner Restoration

Year of search 1965 By R.F. SCHNEIDER
COUNTY BOOK "D" P. 456 2" I.P.

Bearing Trees, Reference Objects

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Bearing Trees, Reference Objects

N. PINE	N. PINE	J. PINE	LOW. POLE
<u>12"</u>	<u>10"</u>	<u>12"</u>	_____
<u>N 9 E</u>	<u>N 21 1/2 W</u>	<u>N 45 1/2 W</u>	<u>N 32 1/2 W</u>
<u>63.4'</u>	<u>250.6'</u>	<u>208.0'</u>	<u>36.9'</u>

Subsequent Corner Restoration

Year surveyed 1998 By Landecker 17008
Location filed CCSO
Monument Certificate of survey indicates monument found

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
CERTIFICATE - AL WELLE - MINN DOT - 1978
Found 1 1/4" pipe (flush). TIES: 14" Norway Pine NNW 250.6'; 12" Jack Pine stump NW 208'; power pole NW 36.98'; 5" Red Oak clump NE 98.86'.
Doc. # 210562