


Index No. C 21

CASS COUNTY LAND CORNER RECORD

T. 138 R. 31 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
E 1/4 2 Corner common to sections 1, 2



EXISTING SURVEYS

Original Government Survey  
 Year surveyed 1870  
 Original monument POST

Bearing Trees  
 Species SPRUCE Y. BIRCH  
 Diameter 6" 8"  
 Bearing S53W S70E  
 Distance 21LKS. 24LKS

Original Evidence Found  
 Year of search \_\_\_\_\_ By \_\_\_\_\_  
 Monument found \_\_\_\_\_

Original Bearing Trees Found  
 Species \_\_\_\_\_  
 Diameter \_\_\_\_\_  
 Bearing \_\_\_\_\_  
 Distance \_\_\_\_\_

Subsequent Corner Restoration  
 Year surveyed 1915 By JOHN CURD  
 Location filed COUNTY RESURVEY "E-47"  
 Monument 2 1/4 x 48" IRON MONUMENT AND GOVT BITS.  
1915, DENNER, BOOK D P. 19 END CORNER AND BOTH GOVT  
BITS. P. 21 - SET 2 1/2 x 48" I.M.  
also on microf. Im - roll 105 BK 53 P 16-17

Bearing Trees, Reference Objects  
 Species microf. Im - roll 105 BK 53 P. 39  
 Diameter set 2 1/4 x 48" I.M. w/cap.  
 Bearing \_\_\_\_\_  
 Distance \_\_\_\_\_

Evidence of Subsequent Corner Restoration  
 Year of search \_\_\_\_\_ By MN/DOT  
Unrecorded cert. of Location indicates  
corner in road 76' NE'ly of M.P. 72

Bearing Trees, Reference Objects			
Ash	Ash	Ash	W. Oak
4"	8"	12"	4"
N45°W	N30°E	S50°E	S35°W
61.26	49.26	79.15	67.26

Subsequent Corner Restoration  
 Year surveyed 1999 By CCSO  
 Location filed CCSO  
 Monument Fd Rail Road spike 3' N. of E.  
Down 0.4'

6" Ash N38°W, 61.12 (MN/DOT nail)  
9" Ash N30°E, 49.05 \*  
4" W. Oak S36°W, 67.32 \*  
P. Pole S3°W, 79.20 \*  
\* distance to double head nail

Evidence of Subsequent Corner Restoration Found  
 Year of search \_\_\_\_\_ By \_\_\_\_\_

Remonumentation certificate prepared \_\_\_\_\_ By \_\_\_\_\_  
 Filed at \_\_\_\_\_ Date \_\_\_\_\_