


Index No. E 21

CASS COUNTY LAND CORNER RECORD

T. 138 R. 31 M. 5TH Coordinates: X _____ Y _____
NE 11 Corner common to sections 4, 2, 11, 12



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1870
Original monument Post

Original Evidence Found

Year of search _____ By _____
Monument found _____

Species	Bearing Trees		
	<u>SUGAR</u>	<u>IRONWOOD</u>	<u>LINDEN</u>
Diameter	<u>8"</u>	<u>6"</u>	<u>12"</u>
Bearing	<u>N7E</u>	<u>S59E</u>	<u>N35W</u>
Distance	<u>32 LKS</u>	<u>10 LKS</u>	<u>30 LKS</u>

Original Bearing Trees Found			
Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1915 By JOHN CURO
Location filed COUNTY RESURVEY "E-47"
Monument 2 1/4 X 48" IRON MONUMENT
1965, R.F. SCHNEIDER, BOOK "D" P. 439 FND CALLED T.I.D.

Evidence of Subsequent Corner Restoration

Year of search 1922 By _____
Co DITCH SURVEY BK 97 BOX 2 OF
Co DITCH SURVEY BOOKS, PG 27

Bearing Trees, Reference Objects

Species	Bearing Trees, Reference Objects		
	<u>W. OAK</u>	<u>W. PINE</u>	<u>T. PINE</u>
Diameter	<u>10"</u>	<u>28"</u>	<u>10"</u>
Bearing	<u>N35E</u>	<u>N78E</u>	<u>N43W</u>
Distance	<u>103.0'</u>	<u>73.9'</u>	<u>47.65'</u>

1965 R.F.S TIES

Bearing Trees, Reference Objects

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Remonumentation certificate prepared _____

By _____

Filed at _____

Date _____