


T. 138 R. 31 M. 5TH Coordinates: X _____ Y _____
NE 12 Corner common to sections 1, 12 AND 6, 7-138-30



EXISTING SURVEYS

Original Government Survey

Year surveyed 1865
Original monument POST

Original Evidence Found

Year of search _____ By _____
Monument found _____

Species	Bearing Trees			
	<u>BL. PINE</u>	<u>BL. PINE</u>	<u>BL. PINE</u>	<u>BL. PINE</u>
Diameter	<u>6"</u>	<u>4"</u>	<u>5"</u>	<u>4"</u>
Bearing	<u>N55E</u>	<u>N33W</u>	<u>S66 1/2 W</u>	<u>S52E</u>
Distance	<u>24 LKS.</u>	<u>17 LKS</u>	<u>50 LKS</u>	<u>10 LKS</u>

Original Bearing Trees Found

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

O = Corner

Subsequent Corner Restoration

Year surveyed 1921 By E. B. HORST
Location filed COUNTY RESURVEY "E-34"
Monument IRON MONUMENT AND GROUT BITS, P. 34
1919, J. H. FLYNN - COUNTY BOOK "E" SET RX 48" I.M.
1920, BEN CLARK. BOOK "C" P. 426, FND 1 1/2" W/COR.

Evidence of Subsequent Corner Restoration

Year of search 1922 By _____
Co DITCH SURVEY BK 97 BOX 2 OF Co
DITCH SURVEY BOOKS, PG 30

Bearing Trees, Reference Objects

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Bearing Trees, Reference Objects

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
CERTIFICATE - AL WELLS - MINN DOT - 1981
Found 3" pipe (down 1'). Set 3/4" x 18"
iron pin in pipe (flush). Ties: Fence post
WEST 36.09'; Fence post East 36.67'.
Doc. #260931.

Dec. 2002 B. Grinna #17253
Cert. of Surv shows Mon. Found

Aug 2003 B. Grinna #17253
Cert. of Surv shows Mon. Found