


Index No. E 5

CASS COUNTY LAND CORNER RECORD

T. 138 R. 31 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
NE 7 Corner common to sections 5, 6, 7, 8



EXISTING SURVEYS

Original Government Survey

Year surveyed 1870  
Original monument lost

Species	Bearing	Trees
<u>W. BIRCH</u>	<u>W. BIRCH</u>	<u>N. PINE</u>
Diameter <u>8"</u>	<u>8"</u>	<u>28"</u>
Bearing <u>S85E</u>	<u>N 2E</u>	<u>N 7 1/2 W</u>
Distance <u>13 LKS.</u>	<u>28 LKS</u>	<u>17 LKS.</u>

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

Original Bearing Trees Found

Species	Bearing	Trees
_____	_____	_____
Diameter _____	_____	_____
Bearing _____	_____	_____
Distance _____	_____	_____

○ = Corner

Subsequent Corner Restoration

Year surveyed 1912 By MELVILLE KEMP  
Location filed COUNTY SURVEY RECORD BOOK "A" P. 589-591  
Monument FIND OLD GOUT BIT STUMP; 28" N. PINE  
N 71-30 W 16 LKS, SET 5x5x30" OAK STAKE  
1916; E.B. HORST, BOOK "B" P 561-563 FIND CORNER  
SET BY KEMP - also on microfilm - roll 105 BK 59  
P. 50, 57

Bearing Trees, Reference Objects			
Species <u>R. OAK</u>	<u>BIRCH STUMP</u>	<u>BIRCH</u>	<u>PINE STUMP</u>
Diameter <u>15"</u>	<u>18"</u>	<u>2"</u>	_____
Bearing <u>N55-03E</u>	<u>N39-22W</u>	<u>S80-35W</u>	<u>S 21-26 E</u>
Distance <u>35.30'</u>	<u>61.00'</u>	<u>50.40'</u>	<u>62.90'</u>

1912 TIES

Evidence of Subsequent Corner Restoration

Year of search 1916 By JOHN LUND  
COUNTY RESURVEY "E-48" 2 1/4 x 48" IRON, M.  
1921 - BEN CLARK - COUNTY RESURVEY "E-48" I, M  
1921 ✓ BOOK "C" P 422 FIND TIES

1982 - Survey Technician T. Freeman & Forester D. Marcum  
Found iron at P.T. of Roads. Cap torn off.  
Bearing Trees, Reference Objects

Species	Bearing	Trees
_____	_____	_____
Diameter _____	_____	_____
Bearing _____	_____	_____
Distance _____	_____	_____

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument October 1912, M.A. Kemp  
Type. rd order indicates corner  
  
April 1916; Type rd. order shows no survey

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_