


Index No. J 17

CASS COUNTY LAND CORNER RECORD

T. 138 R. 31 M. 5TH Coordinates: X _____ Y _____
NE 15 Corner common to sections 10, 11, 14, 15



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1870
Original monument POST

Original Evidence Found

Year of search _____ By _____
Monument found _____

Bearing Trees

Species	Bearing	Trees		
<u>ASH</u>	<u>Tam.</u>	<u>Tam.</u>	<u>ELM</u>	
<u>6"</u>	<u>4"</u>	<u>10"</u>	<u>10"</u>	
<u>N60E</u>	<u>N47W</u>	<u>S74W</u>	<u>S30 1/2 E</u>	
<u>13 LKS</u>	<u>11 LKS</u>	<u>14 LKS</u>	<u>23 LKS</u>	

Original Bearing Trees Found

Species				
_____	_____	_____	_____	_____
_____	_____	_____	_____	_____
_____	_____	_____	_____	_____
_____	_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1915 By JOHN CURO
Location filed COUNTY RESURVEY "E-49"
Monument 2 1/4 x 4 1/8" IRON MONUMENT, GOVT. BITS

Evidence of Subsequent Corner Restoration

Year of search 1922 By _____
CO DITCH SURVEY BK 97 BOX 2 OF C
DITCH SURVEY BOOKS, PG 34

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Bearing Trees, Reference Objects

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Remonumentation certificate prepared _____
Filed at _____

By _____
Date _____