


Index No. V 11

CASS COUNTY LAND CORNER RECORD

T. 138 R. 31 M. 5TH Coordinates: X _____ Y _____
N 1/4 33 Corner common to sections 28, 33



EXISTING SURVEYS

Original Government Survey

Year surveyed 1870
Original monument POST

Original Evidence Found

Year of search _____ By _____
Monument found _____

Bearing Trees

Species TAM TAM _____
Diameter 6" 6" _____
Bearing N55W N39E _____
Distance 6LKS 11LKS _____

Original Bearing Trees Found

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed 10/1915 By J.A. Johnston
Location filed SR 365, Book B, pg. 587
Monument At 2640 from east, no evidence of '14 corner, country badly burned.

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Bearing Trees, Reference Objects

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Remonumentation certificate prepared _____

By _____

Filed at _____

Date _____