


T. 138 R. 32 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
N 1/4 3 Corner common to sections 3 AND 34-139-32



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1860  
Original monument POST

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

Bearing Trees

Species	Bearing	Distance
<u>N. PINE</u>	<u>N 40° W</u>	<u>13 LKS</u>
<u>N. PINE</u>	<u>S 17 1/2° E</u>	<u>49 LKS</u>
_____	_____	_____
_____	_____	_____
_____	_____	_____

Original Bearing Trees Found

Species	Bearing	Distance
_____	_____	_____
_____	_____	_____
_____	_____	_____
_____	_____	_____

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration

Year of search 10 - 1993 By K. DONAGHUE MN/DOT  
SPIKE OVER 4" x 4" CONCRETE MONUMENT  
CERT. OF LOCATION DOC. # 108858

Bearing Trees, Reference Objects

Species	Bearing	Distance
_____	_____	_____
_____	_____	_____
_____	_____	_____
_____	_____	_____

Bearing Trees, Reference Objects

<u>NAIL &amp; DISK</u>	<u>4" J. PINE</u>	<u>N 66° W</u>	<u>83.36</u>
<u>NAIL &amp; DISK</u>	<u>5" POPLAR</u>	<u>S 64° W</u>	<u>125.91</u>
<u>NAIL &amp; DISK</u>	<u>4" BIRCH</u>	<u>S 2° W</u>	<u>78.49</u>
<u>NAIL &amp; DISK</u>	<u>4" J. PINE</u>	<u>N 43° E</u>	<u>59.79</u>

A-15

Subsequent Corner Restoration

Year surveyed 8/2000 By MN/DOT  
Location filed CCSO  
Monument 3/4" Pin with Alum. cap set  
by coordinate value, 1993 monument  
destroyed by construction.  
Cert of Location Doc. # 434533

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_

<u>6" J. Pine</u>	<u>N 52° E</u>	<u>175.51</u>	<u>nail &amp; disk</u>
<u>6" Poplar</u>	<u>S 14° W</u>	<u>119.45</u>	<u>nail &amp; disk</u>
<u>7" Poplar</u>	<u>S 45° W</u>	<u>153.82</u>	<u>nail &amp; disk</u>
<u>5" Poplar</u>	<u>N 33° W</u>	<u>127.21</u>	<u>nail &amp; disk</u>