


Index No. A 17

CASS COUNTY LAND CORNER RECORD

T. 138 R. 32 M. 5TH Coordinates: X _____ Y _____
NE 3 Corner common to sections 2, 3 AND 34, 35-139-32



O = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1860
Original monument POST

Original Evidence Found

Year of search _____ By _____
Monument found _____

	Bearing Trees			
Species	<u>TAM.</u>	<u>TAM.</u>	<u>TAM.</u>	<u>TAM.</u>
Diameter	<u>3"</u>	<u>4"</u>	<u>6"</u>	<u>8"</u>
Bearing	<u>N43 1/2 W</u>	<u>N54 E</u>	<u>S15 1/2 E</u>	<u>S11 W</u>
Distance	<u>36 LKS.</u>	<u>42 LKS</u>	<u>49 LKS</u>	<u>43 LKS</u>

Original Bearing Trees Found			
Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration

Year of search 1-1993 By K. DONAGHUE MN/DOT
4" x 4" CONCRETE MONUMENT
CERT. OF LOCATION DOC. # 408857

Bearing Trees, Reference Objects

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Bearing Trees, Reference Objects

<u>NAIL & DISK</u>	<u>POWDER POLE</u>	<u>N52°W</u>	<u>76.00</u>
<u>NAIL & DISK</u>	<u>CUT OFF POLE</u>	<u>N22°E</u>	<u>44.85</u>
<u>BRIDGE DECK</u>	<u>EDGE</u>	<u>WEST</u>	<u>306'</u>

A-17

Subsequent Corner Restoration

Year surveyed 8/2000 By MN/DOT
Location filed CCSO
Monument 3/4" Pin with Alvin. cap set
by coordinate value, 1993 monument
destroyed by construction.
Cert of location Doc. # 434534

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

P. Pole N36°W, 91.45' nailed disk
E. RCP S11°E, 125.93 chisled "X"
W. RCP S16°W, 124.05 chisled "X"

Remonumentation certificate prepared _____ By _____
Filed at _____ Date _____