


Index No. A 21

CASS COUNTY LAND CORNER RECORD

T. 138 R. 32 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
NE 2 Corner common to sections 1, 2 AND 35, 36-139-32



O = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1860

Original monument POST

Species	Bearing	Trces	
<u>P. PINE</u>	<u>P. PINE</u>	<u>P. PINE</u>	<u>P. PINE</u>
<u>10"</u>	<u>7"</u>	<u>14"</u>	<u>9"</u>
<u>N 67 1/2 E</u>	<u>S 48 E</u>	<u>S 7 1/2 W</u>	<u>N 62 1/4 W</u>
<u>10 LKS</u>	<u>47 LKS</u>	<u>26 LKS</u>	<u>22 LKS</u>

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_

Monument found \_\_\_\_\_

Original Bearing Trees Found

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1912 By JOHN CRO

Location filed COUNTY SURVEY RECORD BOOK "A" P# 08-414

Monument END OLD GOVT B.T.S. P. PINE 10" N 67-30 E 6.6', 7" P. PINE S 48 E 31.0', 14" P. PINE S 7-30 W 17.2', 9" P. PINE N 62-30 W 14.5' SET 8X8X36" CONCRETE POST

Evidence of Subsequent Corner Restoration

Year of search 10-1923 By K. DONAHUE MN/DOT

SPIKE ABOVE 4" x 4" CONCRETE MONUMENT

CERT. OF LOCATION DOC. # 408855

Bearing Trees, Reference Objects

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Bearing Trees, Reference Objects

<u>NAIL &amp; DISK</u>	<u>CR. FE. POST</u>	<u>S 40° W</u>	<u>59.10</u>
<u>NAIL &amp; DISK</u>	<u>CR. FE. POST</u>	<u>S 40° E</u>	<u>55.20</u>
<u>NAIL &amp; DISK</u>	<u>SIGN POST</u>	<u>N 30° E</u>	<u>71.30</u>

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_

Location filed \_\_\_\_\_

Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_

Remonumentation certificate prepared \_\_\_\_\_ By \_\_\_\_\_  
Filed at \_\_\_\_\_ Date \_\_\_\_\_