


Index No. A 7

CASS COUNTY LAND CORNER RECORD

T. 138 R. 32 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
N1/4 5 Corner common to sections 5 AND 32-139-32



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1860  
Original monument Post

Bearing Trees	
Species <u>BL. PINE</u>	<u>BL. PINE</u>
Diameter <u>12"</u>	<u>7"</u>
Bearing <u>N 11/2 W</u>	<u>S 27 E</u>
Distance <u>105 LKS.</u>	<u>86 LKS</u>

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

Original Bearing Trees Found

Species _____	_____
Diameter _____	_____
Bearing _____	_____
Distance _____	_____

Subsequent Corner Restoration

Year surveyed 1908 By JOHN CURD  
Location filed CASS COUNTY SURVEY RECORD BOOK A P. 418  
Monument SET 4x4x48' Post PROTECTION ALLY -474

Bearing Trees, Reference Objects	
Species <u>ALDER</u>	<u>BIRCH</u>
Diameter <u>1 1/2"</u>	<u>1 1/2"</u>
Bearing <u>SW</u>	<u>NW</u>
Distance <u>10.95'</u>	<u>20.95'</u>

Evidence of Subsequent Corner Restoration

Year of search \_\_\_\_\_ By \_\_\_\_\_

Bearing Trees, Reference Objects

_____	_____
_____	_____
_____	_____
_____	_____

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_

Remonumentation certificate prepared \_\_\_\_\_  
Filed at \_\_\_\_\_

By \_\_\_\_\_  
Date \_\_\_\_\_