


Index No. E 15

CASS COUNTY LAND CORNER RECORD

T. 138 R. 32 M. 5TH Coordinates: X _____ Y _____
N 1/4 10 Corner common to sections 3, 10



EXISTING SURVEYS

Original Government Survey
Year surveyed 1870
Original monument POST

Original Evidence Found
Year of search _____ By _____
Monument found _____

Species	Bearing	Trees
<u>BALSAM</u>	<u>SPRUCE</u>	
Diameter <u>6"</u>	<u>10"</u>	
Bearing <u>S41W</u>	<u>N10E</u>	
Distance <u>53 LKS</u>	<u>69 LKS.</u>	

Species	Bearing	Trees
_____	_____	_____
Diameter _____	_____	_____
Bearing _____	_____	_____
Distance _____	_____	_____

Subsequent Corner Restoration
Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration
Year of search MAY 1997 By H. DONAGHUE, MN/DOT
SET CAST IRON MON. FLUSH IN ROAD AT LOST
POSITION
CENT. OF LOCATION ACC. # 433378

Species	Bearing	Reference Objects
_____	_____	_____
Diameter _____	_____	_____
Bearing _____	_____	_____
Distance _____	_____	_____

Species	Bearing	Reference Objects	Distance
<u>N&D</u>	<u>6" ASPEN</u>	<u>S89°E</u>	<u>42.16</u>
<u>N&D</u>	<u>5" ASPEN</u>	<u>S44°E</u>	<u>16.41</u>
<u>N&D</u>	<u>5" ASPEN</u>	<u>S85°W</u>	<u>13.57</u>
<u>N&D</u>	<u>4" BIRCH</u>	<u>N14°W</u>	<u>68.92</u>
<u>STEEL FENCE POST</u>	<u>EAST</u>		<u>1.0</u>

Subsequent Corner Restoration
Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found
Year of search _____ By _____

Remonumentation certificate prepared _____ By _____
Filed at _____ Date _____